

	Type Release Notes	Project/Product CANopen Configuration Tool	
	Name CANopen ConfTool	Project Code CANOPEN CONF	
Author SB	Department R&D	Date 2021-11-24	
Checked	File Name Release Notes.odt	Printed	
Approved		Revision	Classification PUBLIC
			Page 1 (1)
Copyright © TK Engineering Oy. All rights reserved. Reproduction, use or disclosure to third parties without express authority is strictly forbidden.			

CANopen ConfTool 2.1.4

Support for the TKE CAN Switch TCS-10 has been added to the GUI.

This version of CANopen ConfTool have several important bugfixes. A number of issues that affects configuration of bitrate and node-id through the object dictionary have been fixed. Failed firmware updates and a timing issue that affected Windows 10 platforms have been fixed. The log file has been improved to better indicate why a device is not found and parsing of the configuration files have been improved to handle data in different formats.

In this version, official support for Windows Vista, Windows 7 and Windows 8.1 have been dropped. There's nothing preventing you from using ConfTool on older Windows systems but we don't test or support ConfTool on these platforms anymore.

New and Changed Functionality

- #2413 - Removed official support for Windows Vista, Windows 7 and Windows 8.1
- #2044 - Combined WCS-10/TCS-10 model text and graphics in GUI

Bugfixes

- #2504 - Fixed discrepancy in log output between Automatic and Position mode on mismatch.
- #2501 - Product code in DCF now parsed correctly also in automatic mode
- #2489 - <Bitrate> configuration in CFG fixed
- #2483 - <Bitrate> and <Nodeid> configuration in CFG fixed support for subindexes
- #2475 - Configuration stops with core process aborted, fixed
- #2461 - Product code in log no longer mixed up node vs dcf
- #2114 - Updated contact details in help document and ReadMe-file
- #2067 - Improvements to the timeout detection during segmented transfers
- #2036 - Firmware downloading fixed on Windows 10
- #1994 - Better exception handling for the debug outputs
- #1993 - Changed the executable file name to include version number
- #1962 - Improved Structure of Release Folder
- #1934 - Readme file updated

Known Issues

- Does not work with version 2.0.6 of the Castor USB Driver